

## CROSS ARM BRACKETS

Cross arm brackets shall be attached with ASTM A325 connecting bolts or A36 U-bolts for top-mount and side-mount options respectively. Electrical wires should be raced through the center hole in the top plate for top-mounted cross arms or through the hole in the center of the side-mounted attachment plate and then into the appropriate coupling on the pole. Flexible conduit can be used to conceal the wiring, depending upon project requirements or specifications.



Figure 27 - Top-mount Tubular Cross Arm



Figure 26 - Side-mount Tubular Cross Arms



Figure 28 - Side-mount Angle Cross Arm



Figure 29 - Top Mount Cross Arm



Figure 30 - Tubular Cross Arm



Figure 31 - Angle Cross Arm